INSPECTION SHEET 検品書 LIFTING PLATFORM 高所作業車

INSPECTION DATE		2025/8/20 MAKE		≣	TADANO		MODEL BT-110-1		
SERIAL No.	PLATE: HB5374			STAMP: NOT FOUND					
HR METER	412	26 HR	Odometer		118889	kr	n YEAR	2008	YR
CHASSIS	MODEL NPR81				No. 7008630				
SHOE					TIRE SIZE			215/70R17.5	
MAX HIGHT	6.8 m				MAX WEIGH	łΤ	200 kg		
ENGINE : MODEL S/N					INTERIOR See Photos. 写真参照				
Oil leakage	FAIR · Attn				INTERIOR COND. CLEAN - FAIR - DIRTY				
Blow-By	FAIR) · Attn	A LITTLE • N	IIDDLE · SEV	'ERE	Operator's Seat	FAIR) · A	ttn		
Sound	FAIR) · Attn				Glasses	FAIR) · A	ttn		
Oil	FAIR) · Attn				AirCon (A/C)	· H/C	• H only • C only •	None
Exhaust Color									
US EPA	YES (NO)				RUST (5: NONE,	4: A LIT	TLE, 3: MIDI	DLE, 2: MUCH, 1: CORRODED)	4
OPERATION PUMP					TIRE WEAR FAIR • WORN • UNEVEN WEAR				
Sound	FAIR · Attn				COMMENT				
Oil leakage	FAIR · Attn								
Power	FAIR · Attn								
COOLING SYSTEM					OUTRIGGERS X · (H)				
Radiator	FAIR · Attn				OUTRIGGERS C	OND. F	AIR • (Attn	*1	
Oil Cooler FAIR) · Attn					COMMENT				
TRANSMISSION & TRAVEL					橋梁点検車 BRIDGE CHECKER				
T/M TYPE	АТ). мт		3 GEARS	発電機使用不可(798HR) GENERATOR: UNABLE TO USE (798HR)					
Transmission	FAIR) · Attn				*1 右Rスライドしきらない				
4WD	4WD (2WD)				*1 REAR RIGHT SLIDE CYLINDER: UNABLE TO EXTEND COMPLETELY				
Travel	FAIR) · Attn								
Swing	FAIR) · Attn								
FOOT BRAKE	FAIR) · Attn								
PARKING BRAKE	FAIR) · Attn								
воом									
No. of S	ection	1 SECTIONS							
DERRICKI	NG CYL.	FAIR • Attn							
EXTENSION CYL. FAIR) · Attn					RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。