

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/20	MAKE	KUBOTA	MODEL	U-55-6E
SERIAL	KBCDZ56AKR3B31148			STAMP	KBCDZ56AKR3B31148
HR METER	521	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	400R

ENGINE : MODEL		S/N	8PA1259
Oil leakage	<u>FAIR</u> • Attn		
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	<u>FAIR</u> • Attn		
Oil	<u>FAIR</u> • Attn		
Exhaust Color	<u>FAIR</u> • Attn		
US EPA	YES • <u>NO</u>		
MAIN PUMP			
Sound	<u>FAIR</u> • Attn		
Oil leakage	<u>FAIR</u> • Attn		
Power	<u>FAIR</u> • Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> • Attn		
Oil Cooler	<u>FAIR</u> • Attn		
OPERATING SYSTEM			
Swing	<u>FAIR</u> • Attn		
Travel	<u>FAIR</u> • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY		
Operator's Seat	<u>FAIR</u> • Attn		
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • <u>None</u>		
BOOM / ARM / BKT			
Boom	<u>FAIR</u> • Attn		
Boom Cylinder	<u>FAIR</u> • Attn		
Arm	<u>FAIR</u> • Attn		
Arm Cylinder	<u>FAIR</u> • Attn		
ATTACHMENT	<u>FAIR</u> • Attn		
BKT Cylinder	<u>FAIR</u> • Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD • <u>SLOPE</u> NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	MULTI • <u>2</u> • NO
ARM-CRANE	YES • <u>NO</u>
BLADE	<u>YES</u> • NO
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	<u>YES</u> • NO Breaker only • <u>Multi</u>
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。