

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2025/8/21	MAKE	KOMATSU	MODEL	FD160E-8		
SERIAL	7507			STAMP	M247-7507		
HR METER	9363	HR	Odometer	-	km	YEAR	YR
CAB/CNP	CAB	/	CNP	/	NONE	TIRE SIZE	11.00-20
MAX LIFTING HEIGHT	2.9	m	VIEW	MONO	FORK LENGTH	2500	mm
FORK SPEC	フォークシフト POSITIONER						

ENGINE : MODEL 6D107E-1 S/N 26544518					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE	*1	
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	FAIR	(Attn)	黒煙小 A LITTLE BLACK FUMES		
US EPA	(YES)	NO			
OPERATION PUMP					
Sound	FAIR	(Attn)	異音あり NOISES		
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	(PS)	DD			
Transmission	(FAIR)	Attn			
Travel	(FAIR)	Attn			
FOOT BRAKE	(FAIR)	Attn			
PARKING BRAKE	(FAIR)	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · (FAIR) · DIRTY				
Operator's Seat	(FAIR)	Attn			
Glasses	FAIR	Attn			
AirCon	A/C · H/C · H only · C only · (None)				
HYDRAULICS					
MAST Cylinder	(FAIR)	Attn			
TILT Cylinder	(FAIR)	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				2	
TIRE WEAR		FAIR · WORN · (UNEVEN WEAR)			
COMMENT					
エアー圧力低下警告灯消えない WARNING LAMP FOR LOW AIR PRESSURE: UNABLE TO LIGHT OFF 左側ステアリングシリンダー油漏れあり LEFT STEERING CYLINDER: OIL LEAKING *1 ブローバイ吐出し口から油漏れあり *1 BLOW-BY DISCHARGE PORT: OIL LEAKING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					
1					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。