

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/18	MAKE	CAT	MODEL	910K
SERIAL	CAT0910KTAY400458			STAMP	CAT0910KTAY400458
HR METER	634	HR	Odometer	—	km
YEAR	2014			YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

ENGINE : MODEL		C3.8	S/N	2EC2978
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn A LITTLE • MIDDLE • SEVERE		
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	NO		
OPERATION PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	☒ PS	DD		
Transmission	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
FOOT BRAKE	☒ FAIR	Attn		
PARKING BRAKE	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	☒ CLEAN	FAIR • DIRTY		
Operator's Seat	☒ FAIR	Attn		
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	H/C • H only • C only • None		
FRONT & CYLINDERS				
Arm	☒ FAIR	Attn		
Bell crank	☒ FAIR	Attn		
Bucket	☒ FAIR	Attn		
Articulate	☒ FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	☒ FAIR • WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES • NO
ATTACHMENTS	
STD BKT	YES • ☒ OTHER スノーブレード SNOW BLADE
BLADE	YES • ☒ NO Piping for Tilt ☒ YES • NO
COMMENT	
左サイドカバーラッチ破損あり LEFT SIDE COVER LATCH: BROKEN	
ワンタッチ付 W/ONE-TOUCH	
付属品:スタンダードバケット STANDARD BUCKET AS SPARE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
5	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。