

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/20	MAKE	CAT	MODEL	325FLCR
SERIAL	CAT0325FCRBW20828		STAMP	CAT0325FCRBW20828	
HR METER	8669 / 8672	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		C4.4	S/N
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	ステッカー読み取り不可 STICKER: UNREADABLE
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	*1
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only ・ C only ・ None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	少し自然降下あり A LITTLE HYDRAULIC DRIFT
Arm Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER ())
Lever	LONG ▪ (WRIST)
Multi	(MULTI) ▪ 2 ▪ NO
ARM-CRANE	YES ▪ (NO)
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	(YES) ▪ NO (Breaker only) ▪ Multi *2
COMMENT	
*1 上下調節ができない SEAT LIFTER: UNABLE TO ADJUST	
*2 ペダルなし、動作未確認 NO PEDAL, OPERATION: NOT CHECKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。