

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/29	MAKE	KOMATSU	MODEL	WA80-8
SERIAL	20663		STAMP	KMTWA139CME020663	
HR METER	8054	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	17.5/65-20	

<table style="width: 100%;"> <tr> <td colspan="2">ENGINE : MODEL</td> <td>S/N</td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Blow-By</td> <td>☒ FAIR · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES · ☒ NO</td> <td></td> </tr> <tr> <td colspan="3">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil leakage</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Power</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>☒ PS · DD</td> <td></td> </tr> <tr> <td>Transmission</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Travel</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>FOOT BRAKE</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>PARKING BRAKE</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td colspan="3">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN · ☒ FAIR ·</td> <td>DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Glasses</td> <td>☒ FAIR · ☒ Attn</td> <td>*1</td> </tr> <tr> <td>AirCon</td> <td>☒ A/C · H/C · H only · C only · None</td> <td></td> </tr> <tr> <td colspan="3">FRONT & CYLINDERS</td> </tr> <tr> <td>Arm</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Bell crank</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Bucket</td> <td>☒ FAIR · Attn</td> <td></td> </tr> <tr> <td>Articulate</td> <td>☒ FAIR · Attn</td> <td></td> </tr> </table>	ENGINE : MODEL		S/N	Oil leakage	☒ FAIR · Attn		Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	Sound	☒ FAIR · Attn		Oil	☒ FAIR · Attn		Exhaust Color	☒ FAIR · Attn		US EPA	YES · ☒ NO		OPERATION PUMP			Sound	☒ FAIR · Attn		Oil leakage	☒ FAIR · Attn		Power	☒ FAIR · Attn		COOLING SYSTEM			Radiator	☒ FAIR · Attn		Oil Cooler	☒ FAIR · Attn		TRANSMISSION & TRAVEL			T/M TYPE	☒ PS · DD		Transmission	☒ FAIR · Attn		Travel	☒ FAIR · Attn		FOOT BRAKE	☒ FAIR · Attn		PARKING BRAKE	☒ FAIR · Attn		INTERIOR See Photos. 写真参照			INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY	Operator's Seat	☒ FAIR · Attn		Glasses	☒ FAIR · ☒ Attn	*1	AirCon	☒ A/C · H/C · H only · C only · None		FRONT & CYLINDERS			Arm	☒ FAIR · Attn		Bell crank	☒ FAIR · Attn		Bucket	☒ FAIR · Attn		Articulate	☒ FAIR · Attn		<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>4</td> </tr> <tr> <td>TIRE WEAR</td> <td>☒ FAIR · WORN · UNEVEN WEAR</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING</td> </tr> <tr> <td>RIDE CONTROL</td> <td>YES · ☒ NO</td> </tr> <tr> <td colspan="2">ATTACHMENTS</td> </tr> <tr> <td>STD BKT</td> <td>☒ YES · OTHER</td> </tr> <tr> <td>BLADE</td> <td>YES · ☒ NO Piping for Tilt YES · ☒ NO</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">A/C不良 A/C: MALFUNCTION</td> </tr> <tr> <td colspan="2">*1 右Fひびあり FRONT RIGHT PART OF WINDSHIELD: CRACKED</td> </tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">4</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR	COMMENT		STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING		RIDE CONTROL	YES · ☒ NO	ATTACHMENTS		STD BKT	☒ YES · OTHER	BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO	COMMENT		A/C不良 A/C: MALFUNCTION		*1 右Fひびあり FRONT RIGHT PART OF WINDSHIELD: CRACKED		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	
ENGINE : MODEL		S/N																																																																																																																					
Oil leakage	☒ FAIR · Attn																																																																																																																						
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																																					
Sound	☒ FAIR · Attn																																																																																																																						
Oil	☒ FAIR · Attn																																																																																																																						
Exhaust Color	☒ FAIR · Attn																																																																																																																						
US EPA	YES · ☒ NO																																																																																																																						
OPERATION PUMP																																																																																																																							
Sound	☒ FAIR · Attn																																																																																																																						
Oil leakage	☒ FAIR · Attn																																																																																																																						
Power	☒ FAIR · Attn																																																																																																																						
COOLING SYSTEM																																																																																																																							
Radiator	☒ FAIR · Attn																																																																																																																						
Oil Cooler	☒ FAIR · Attn																																																																																																																						
TRANSMISSION & TRAVEL																																																																																																																							
T/M TYPE	☒ PS · DD																																																																																																																						
Transmission	☒ FAIR · Attn																																																																																																																						
Travel	☒ FAIR · Attn																																																																																																																						
FOOT BRAKE	☒ FAIR · Attn																																																																																																																						
PARKING BRAKE	☒ FAIR · Attn																																																																																																																						
INTERIOR See Photos. 写真参照																																																																																																																							
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY																																																																																																																					
Operator's Seat	☒ FAIR · Attn																																																																																																																						
Glasses	☒ FAIR · ☒ Attn	*1																																																																																																																					
AirCon	☒ A/C · H/C · H only · C only · None																																																																																																																						
FRONT & CYLINDERS																																																																																																																							
Arm	☒ FAIR · Attn																																																																																																																						
Bell crank	☒ FAIR · Attn																																																																																																																						
Bucket	☒ FAIR · Attn																																																																																																																						
Articulate	☒ FAIR · Attn																																																																																																																						
UNDERCARRIAGE : See Photos. 写真参照																																																																																																																							
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																																																																						
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR																																																																																																																						
COMMENT																																																																																																																							
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING																																																																																																																							
RIDE CONTROL	YES · ☒ NO																																																																																																																						
ATTACHMENTS																																																																																																																							
STD BKT	☒ YES · OTHER																																																																																																																						
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO																																																																																																																						
COMMENT																																																																																																																							
A/C不良 A/C: MALFUNCTION																																																																																																																							
*1 右Fひびあり FRONT RIGHT PART OF WINDSHIELD: CRACKED																																																																																																																							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																							
4																																																																																																																							

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。