

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/18	MAKE	KOBELCO	MODEL	SK235SRDLC-2
SERIAL	?U06-03329 SOME LETTER: UNREADABLE			STAMP	YU06-03329
HR METER	9612	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		J05E	S/N
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	にじみあり OIL OOZING
Power	FAIR	Attn	*2
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C · H only · C only · None	
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
底板周り油漏れ小 BOTTOM: OIL LEAKING	
BKT	STD / SLOPE / NARROW / SKELETON OTHER BREAKER
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5
COMMENT	
エレベータCAB ELEVATOR CAB	
ブーム下ホースひび割れ、にじみあり	
SOME HOSE AROUND LOWER PART OF BOOM: CRACKED, OIL OOZING	
ブーム横ホースひび割れあり SOME HOSE AROUND BOOM: CRACKED	
旋回モーター周り油汚れあり AROUND SWING MOTOR: OIL STAINS	
A/C冷えない A/C: MALFUNCTION	
*1 油漏れ小(E/G下おしめあり)	
*1 OIL LEAKING (BOTTOM OF ENGINE: W/ABSORPTION MAT)	
*2 ブームで本体上がらない(少しだけ浮き上がる)	
*2 UNABLE TO PUSH UP THE BODY BY BOOM ENOUGH	
(ABLE TO PUSH UP A LITTLE)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。