

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/7	MAKE	KOMATSU	MODEL	PC35MR-2
SERIAL	7703			STAMP	KMTPC096E05007703
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	300G

ENGINE : MODEL 3D88E S/N 03539

Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	<u>YES</u> · NO	

MAIN PUMP

Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	

COOLING SYSTEM

Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	

OPERATING SYSTEM

Swing	<u>FAIR</u> · <u>Attn</u>	若干ゴリゴリ感あり A LITTLE RATTLING
Travel	<u>FAIR</u> · <u>Attn</u>	増速S/W不良 HI/LO SWITCH: MALFUNCTION

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY
Operator's Seat	<u>FAIR</u> · Attn
Glasses	<u>FAIR</u> · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>

BOOM / ARM / BKT

Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · <u>Attn</u>	補修跡あり REPAIRED
Arm Cylinder	<u>FAIR</u> · Attn	
ATTACHMENT	<u>FAIR</u> · <u>Attn</u>	ガタ大 MUCH LOOSE
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

COMMENT

.....

.....

.....

.....

BKT STD / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

HRメーター不良 HR METER: MALFUNCTION

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。