## INSPECTION SHEET 検品書 ROLLER ローラー

INSPECTION	ON DATE	N DATE 2025/8/19			SAKAI		MODEL	R2		
SERIAL	10652			-	STAMP			RR3-10652		
HR METER	2	888 HR Oc	lometer		_		km YEAR	`	ΥR	
CAB/CNP	ROPS CA	AB / CAB / ROPS C	NP / CNP	NONE	TIRE SIZ	ĽΕ	,	_		
ENGINE : MODEL S/N					UNDERCARRIAGE: See Photos. 写真参照					
Oil leakage	FAIR) · Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3						
Blow-By	FAIR · Attn	A LITTLE · MIDDLE •	SEVERE		TIRE WE	AR	FAIR • W	ORN • UNEVEN WEAR		
Sound	FAIR · Attn				COMMENT	-				
Oil	FAIR · Attn				*1 給水タン	ノク水	抜きキャップ	プ欠、水溜まらない		
Exhaust Color	FAIR · Attn				*1 WATER TA	NK DR	AIN CAP: MISS	ING, UNABLE TO STORE ANY	WATER	
US EPA	YES · NO									
OPERATIO										
Sound	FAIR · Attn									
Oil leakage	FAIR · Attn									
Power	FAIR · Attn									
COOLING	SYSTEM									
Radiator	FAIR · Attn									
Oil Cooler	FAIR · Attn									
TRANSMIS	SSION &	TRAVEL								
T/M TYPE	PS) · DD									
Transmission	FAIR · Attn									
Travel	FAIR · Attn									
FOOT BRAKE	FAIR · Attn									
PARKING BRAKE	FAIR · Attn									
INTERIOR	See	Photos. 写真参照								
INTERIOR COND.	CLEAN	· FAIR • [	DIRTY							
Operator's Seat	FAIR · Attn	破れあり HUGE CUT	S							
Glasses	FAIR · Attn			_						
AirCon	A/C ·	H/C · H only ·	C only •	None						
OTHERS	•									
Vibratory	FAIR · Attn									
Watering	FAIR · (Attn	*1								
Articulate	FAIR · Attn				RUST of BODY	(5: NONE	E, 4: A LITTLE, 3:	MIDDLE, 2: MUCH, 1: CORRODED)	2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。