

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/19	MAKE	CAT	MODEL	320E-2
SERIAL	CAT0320EPAWS00324			STAMP	CAT0320EPAWS00324
HR METER	9417 / 9453	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL						C6.6	S/N	C8N35479
Oil leakage	(FAIR)	Attn						
Blow-By	(FAIR)	Attn	A LITTLE	MIDDLE	SEVERE			
Sound	(FAIR)	Attn						
Oil	(FAIR)	Attn						
Exhaust Color	(FAIR)	Attn						
US EPA	YES	(NO)						
MAIN PUMP								
Sound	(FAIR)	Attn						
Oil leakage	(FAIR)	Attn						
Power	(FAIR)	Attn						
COOLING SYSTEM								
Radiator	(FAIR)	Attn						
Oil Cooler	(FAIR)	Attn						
OPERATING SYSTEM								
Swing	(FAIR)	Attn						
Travel	(FAIR)	Attn						
INTERIOR See Photos. 写真参照								
INTERIOR COND.	CLEAN	(FAIR)	DIRTY					
Operator's Seat	(FAIR)	Attn	破れあり CUTS					
Glasses	(FAIR)	Attn						
AirCon	(A/C)	H/C	H only	C only	None			
BOOM / ARM / BKT								
Boom	(FAIR)	Attn						
Boom Cylinder	FAIR	(Attn)	右側にじみあり RIGHT CYLINDER:	OIL OOZING				
Arm	(FAIR)	Attn						
Arm Cylinder	(FAIR)	Attn						
ATTACHMENT	(FAIR)	Attn						
BKT Cylinder	FAIR	(Attn)	油漏れ小 OIL LEAKING					

UNDERCARRIAGE :						See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3		
COMMENT								
スイベル、スイベル下にじみあり								
SWIVEL & BOTTOM OF SWIVEL: OIL OOZING								
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()						
Lever	LONG	(WRIST)						
Multi	(MULTI)	2 NO						
ARM-CRANE	YES	(NO)						
BLADE	YES	(NO)						
OFFSET	YES	(NO)						
OFFSET Cylinder	FAIR	Attn						
Piping	(YES) NO	Breaker only Multi						
COMMENT								
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。