

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/19	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	28126		STAMP	KMTPC189T01028126	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		4D95LE-5	S/N	529015
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
				None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	両側油漏れ小 CYLINDERS: OIL LEAKING	
Arm	FAIR	Attn	ガタあり LOOSE	
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2
COMMENT					
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER())				
Lever	LONG	▪	(WRIST)		
Multi	MULTI	▪	2	▪	(NO)
ARM-CRANE	YES	▪	(NO)		
BLADE	(YES)	▪	NO		
OFFSET	YES	▪	(NO)		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	(YES)	▪	NO	Breaker only ▪ Multi	*1
COMMENT					
ボディヘコミ多数あり BODY: DEFORMED					
全サイドカバーラッチ不良 ALL SIDE COVER LATCHES: MALFUNCTION					
左前後サイドカバー番線留めあり LEFT SIDE COVERS: FIXED WITH WIRES					
ウインチ付(動作未確認) W/WINCH (OPERATION: NOT CHECKED)					
A/Cエラー表示あり A/C ERROR DISPLAY					
*1 油圧掛からない UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。