

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/20	MAKE	KOMATSU	MODEL	WA320-5		
SERIAL	60542			STAMP	W105-60542		
HR METER	12384	HR	Odometer	42180	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25		

ENGINE : MODEL		6D102E-2	S/N	26346992
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	*1

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY				
Operator's Seat	FAIR •	Attn	ガタ、破れあり LOOSE, TORN		
Glasses	FAIR •	Attn			
AirCon	A/C •		H/C •	H only •	C only • None

FRONT & CYLINDERS

Arm	FAIR	Attn	
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	シリンダー油漏れ小 CYLINDER: OIL LEAKING
Articulate	FAIR	Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

TIRE WEAR FAIR • WORN • UNEVEN WEAR

COMMENT

Fタイヤ横ホースひび割れあり

SOME HOSES AROUND FRONT TIRES: CRACKED

リアデフ周り油漏れあり AROUND REAR DIFFERENTIAL: OIL LEAKING

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	YES	☒ NO
--------------	-----	-------------------------------------

ATTACHMENTS

STD BKT	(YES) • OTHER	
---------	---------------	--

BLADE	YES	☒ NO	Piping for Tilt	YES	☒ NO
-------	-----	-------------------------------------	-----------------	-----	-------------------------------------

COMMENT

CAB下ホース油汚れあり SOME HOSES UNDER CAB: OIL STAINS

E03表示あり “E03” ERROR DISPLAY

ワンタッチ付 W/ONE-TOUCH

*1 効き甘い、解除してもランプ消えない

*1 BRAKE: LOOSE, PARKING LAMP: NOT LIGHTING OFF

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。