

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/26	MAKE	KOMATSU	MODEL	PC138US-11
SERIAL	54339		STAMP	KMTPC261EKA054339	
HR METER	8697	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR DIRTY
Operator's Seat	FAIR	Attn
Glasses	FAIR	Attn
AirCon	A/C	H/C H only C only None
BOOM / ARM / BKT		
Boom	FAIR	Attn
Boom Cylinder	FAIR	Attn
Arm	FAIR	Attn
Arm Cylinder	FAIR	Attn
ATTACHMENT	FAIR	Attn
BKT Cylinder	FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD	SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG	WRIST
Multi	MULTI · 2	NO
ARM-CRANE	YES	NO
BLADE	YES	NO
OFFSET	YES	NO
OFFSET Cylinder	FAIR	Attn
Piping	YES	NO Breaker only Multi
COMMENT		
L03、L01エラー表示あり		
(定置手動再生要、KDPF系統異常、尿素SCRシステム異常)		
"L03" & "L01" ERRORS DISPLAY		
FOR STATIONARY MANUAL REGENERATION REQUIRED,		
DIESEL PARTICULATE FILTER, & UREA SCR SYSTEM		
各カメラ曇りあり AROUND VIEW MONITOR: BLURRED		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。