

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/3	MAKE	HITACHI	MODEL	ZX120-6
SERIAL	HCMDAQA0H00512576			STAMP	HCMDAQA0H00512576
HR METER	8877	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL		4JJ1	S/N	290754
Oil leakage	(FAIR)	Attn		
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	(FAIR)	Attn		
Oil	(FAIR)	Attn		
Exhaust Color	(FAIR)	Attn		
US EPA	(YES)	NO		
MAIN PUMP				
Sound	(FAIR)	Attn		
Oil leakage	(FAIR)	Attn		
Power	(FAIR)	Attn		
COOLING SYSTEM				
Radiator	(FAIR)	Attn		
Oil Cooler	(FAIR)	Attn		
OPERATING SYSTEM				
Swing	(FAIR)	Attn		
Travel	(FAIR)	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · (FAIR) · DIRTY			
Operator's Seat	FAIR · (Attn)	汚れあり DIRTY		
Glasses	(FAIR)	Attn		
AirCon	(A/C) · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	(FAIR)	Attn		
Boom Cylinder	(FAIR)	Attn		
Arm	(FAIR)	Attn		
Arm Cylinder	(FAIR)	Attn		
ATTACHMENT	(FAIR)	Attn		
BKT Cylinder	(FAIR)	Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT			
足周り石灰汚れあり LIME STAINS			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · (WRIST)		
Multi	MULTI · 2 · (NO)		
ARM-CRANE	YES · (NO)		
BLADE	YES · (NO)		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	YES · (NO)	Breaker only · Multi	
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。