

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/21	MAKE	TADANO	MODEL	GR-500N-1
SERIAL No.	PLATE : 582771		STAMP : TR552-0191		
HR METER	847 + 13036 HR		Odometer	6974 + 74783 km	
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL	S/N
Oil leakage	FAIR · Attn
Blow-By	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR	Attn	
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY				
Operator's Seat	FAIR •	Attn			
Glasses	FAIR •	Attn			
AirCon	A/C •	H/C •	H only •	C only •	None

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	51t, 25t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		4
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

OUTRIGGERS

OUTRIGGERS	☒ H			
OUTRIGGERS COND.	☒ Attn			
Oil leakage (JACK CYL.)	FRONT	L • R	REAR	L • R
Oil leakage (SLIDE CYL.)	FRONT	L • R	REAR	L • R

COMMENT

--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。