

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/21	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB3933		STAMP : TR256-0651		
HR METER	19657	HR	Odometer	192317	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE :	MODEL	S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR	Attn	ホース付近にじみあり AROUND HOSE: OIL OOZING
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only • C only • None

COMMENT

BOOM

No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn
DERRICKING CYL.	FAIR	▪ Attn
EXTENSION CYL.	FAIR	▪ Attn
JIB	YES	▪ NO
JIB TYPE	STD	▪ PWR
MAIN & SUB WIRE	YES	▪ NO
FREE FALL	YES	▪ NO
HOOK	25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		4
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

OUTRIGGERS

OUTRIGGERS	☒ X	▪	H			
OUTRIGGERS COND.	☒ FAIR	▪	Attn			
Oil leakage (JACK CYL.)	FRONT	L	▪	R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪	R	REAR	L ▪ R

COMMENT

[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。