INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2025/8/21	CATEGORY	MOBILE CRUSHER				
MAKE	KOMATSU			MODEL	BR100J-1		
SERIAL	1040			STAMP	NOT FOUND		
HR METER	6712 HR	Odometer	km	YEAR	YR		
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE	450G	TIRE			

ENGINE	**MODEL** 4D95L-1		**S/N** 202384	
Oil leakage	FAIR・Attn		Oil	FAIR・Attn
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE	Exhaust Color	FAIR・Attn
Sound	FAIR・Attn		EPA	YES・NO

CONDITION	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR ・WORN・UNEVEN WEAR
COMMENT			
エンジン油汚れあり ENGINE: OIL STAINS			
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。