

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/26	MAKE	TADANO	MODEL	TR-200M-4
SERIAL No.	PLATE : 521437			STAMP : TR202-0283	
HR METER	8179	HR	Odometer	72341	km
TIRE SIZE	14.00R24			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR ☐ Attn	
Blow-By	☒ FAIR ☐ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE
Sound	☒ FAIR ☐ Attn	
Oil	☒ FAIR ☐ Attn	
Exhaust Color	☒ FAIR ☐ Attn	

OPERATION PUMP		
Sound	☒ FAIR ☐ Attn	
Oil leakage	☒ FAIR ☐ Attn	
Power	☒ FAIR ☐ Attn	

COOLING SYSTEM		
Radiator	☒ FAIR ☐ Attn	
Oil Cooler	☒ FAIR ☐ Attn	

OPERATING SYSTEM		
Computer	OK ☒ NG ☐ *1	
Swing	☒ FAIR ☐ Attn	
Travel	☒ FAIR ☐ Attn	

TRANSMISSION		
Transmission	☒ FAIR ☐ Attn	
No. OF GEARS	3 GEARS	
4WD	☒ 4WD ☐ 6WD	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☒ FAIR ☐ DIRTY	
Operator's Seat	☒ FAIR ☐ Attn	破れあり HUGE CUTS
Glasses	☒ FAIR ☐ Attn	
AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None	

COMMENT		

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	☒ FAIR ☐ Attn	
DERRICKING CYL.	☒ FAIR ☐ Attn	
EXTENSION CYL.	☒ FAIR ☐ Attn	
JIB	YES ☐ NO ☒	
JIB TYPE	STD ☐ PWR	
MAIN & SUB WIRE	YES ☐ NO ☒ *2	
FREE FALL	YES ☒ NO ☐	
HOOK	20t, BALL	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		2
TIRE WEAR	FAIR ☒ WORN ☐ UNEVEN WEAR	

COMMENT		

OUTRIGGERS				
OUTRIGGERS	☒ X ☐ H			
OUTRIGGERS COND.	☒ FAIR ☐ Attn			
Oil leakage (JACK CYL.)	FRONT	L ☐ R ☐	REAR	L ☐ R ☐
Oil leakage (SLIDE CYL.)	FRONT	L ☐ R ☐	REAR	L ☐ R ☐

COMMENT		
*1 過巻エラー音あり、非常用にて作動		
*1 WARNING SOUNDS FOR OVERWINDING PREVENTION ERROR: ON, ABLE TO OPERATE IN THE EMERGENCY MODE		
*2 補巻ワイヤーなし AUXILIARY HOISTING WIRE: MISSING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。