

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/5	MAKE	TADANO	MODEL	TR-100M-1
SERIAL No.	PLATE : FC1078		STAMP : TR100-1078		
HR METER	14028	HR	Odometer	124698	km
TIRE SIZE	11R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Computer	OK • NG	
Swing	FAIR • Attn	
Travel	FAIR • Attn	
TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	3 GEARS	
4WD	4WD • 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
COMMENT		

BOOM									
No. of Section		6		SECTIONS					
CRACK/ENFORCEMENT		FAIR		▪ Attn					
DERRICKING CYL.		FAIR		▪ Attn					
EXTENSION CYL.		FAIR		▪ Attn					
JIB		YES		▪ NO					
JIB TYPE		STD		▪ PWR					
MAIN & SUB WIRE		YES		▪ NO					
HOOK		4.9t, BALL							
UNDERCARRIAGE : See Photos. 写真参照									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								4	
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR							
COMMENT									
リヤステ不良 REAR STEERING: MALFUNCTION									
OUTRIGGERS									
OUTRIGGERS		X		▪ H					
OUTRIGGERS COND.		FAIR		▪ Attn					
Oil leakage (JACK CYL.)		FRONT		L ▪ R		REAR		L ▪ R	
Oil leakage (SLIDE CYL.)		FRONT		L ▪ R		REAR		L ▪ R	
COMMENT									
エアー漏れ大 MUCH AIR LEAKING									
Pブレーキ効きが悪い PARKING BRAKE: LOOSE									
フリーフォール付 FREE FALL: YES									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。