

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/26	MAKE	KATO	MODEL	KR-65H
SERIAL No.	PLATE :	0311165	STAMP :	KRC002-1165	
HR METER	27794	HR	Odometer	106403	km
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL		S/N	
Oil leakage	FAIR	Attrn	E/G下部にじみあり BOTTOM: OIL Oozing
Blow-By	FAIR	Attrn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attrn	
Oil	FAIR	Attrn	
Exhaust Color	FAIR	Attrn	
OPERATION PUMP			
Sound	FAIR	Attrn	
Oil leakage	FAIR	Attrn	
Power	FAIR	Attrn	
COOLING SYSTEM			
Radiator	FAIR	Attrn	
Oil Cooler	FAIR	Attrn	
OPERATING SYSTEM			
Computer	OK	NG	
Swing	FAIR	Attrn	
Travel	FAIR	Attrn	
TRANSMISSION			
Transmission	FAIR	Attrn	
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR ·	DIRTY	
Operator's Seat	FAIR	Attrn	
Glasses	FAIR	Attrn	
AirCon	A/C ·	H/C · H only · C only · None	
COMMENT			

BOOM					
No. of Section	6		SECTIONS		
CRACK/ENFORCEMENT	FAIR	▪ Attn			
DERRICKING CYL.	FAIR	▪ Attn			
EXTENSION CYL.	FAIR	▪ Attn			
JIB	YES	▪ NO			
JIB TYPE	STD	▪ PWR			
MAIN & SUB WIRE	YES	▪ NO			
FREE FALL	YES	▪ NO			
HOOK	65t, 34t, BALL, HANGER				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					4
TIRE WEAR	FAIR ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X	▪ H			
OUTRIGGERS COND.	FAIR	▪ Attn			
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。