

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/22	MAKE	KOBELCO	MODEL	SK135SRD-5
SERIAL	YY08040312		STAMP	YY08040312	
HR METER	2124	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		4JJ1	S/N	271747
Oil leakage	☒ FAIR	Attn		
Blow-By	☒ FAIR	Attn A LITTLE · MIDDLE · SEVERE		
Sound	☒ FAIR	Attn		
Oil	☒ FAIR	Attn		
Exhaust Color	☒ FAIR	Attn		
US EPA	☒ YES	NO		
MAIN PUMP				
Sound	☒ FAIR	Attn		
Oil leakage	☒ FAIR	Attn		
Power	☒ FAIR	Attn		
COOLING SYSTEM				
Radiator	☒ FAIR	Attn		
Oil Cooler	☒ FAIR	Attn		
OPERATING SYSTEM				
Swing	☒ FAIR	Attn		
Travel	☒ FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	☒ CLEAN	FAIR · DIRTY		
Operator's Seat	☒ FAIR	Attn 破れあり CUTS		
Glasses	☒ FAIR	Attn		
AirCon	☒ A/C	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	☒ FAIR	Attn		
Boom Cylinder	☒ FAIR	Attn		
Arm	☒ FAIR	Attn		
Arm Cylinder	☒ FAIR	Attn		
ATTACHMENT	☒ FAIR	Attn		
BKT Cylinder	☒ FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT STD / SLOPE / NARROW / SKELETON / ☒ OTHER) Lever LONG · ☒ WRIST Multi ☒ MULTI · 2 · NO ARM-CRANE YES · ☒ NO BLADE YES · ☒ NO OFFSET YES · ☒ NO OFFSET Cylinder FAIR · Attn Piping ☒ YES · NO Breaker only · Multi 5	
COMMENT	
アタッチメント: 回転式フォークグラブ ATTACHMENT: ROTATABLE FORK GRAB MAKE: TAGUCHI GV-120S ワンタッチ付 W/ONE-TOUCH ブーム背面ホースひび割れあり SOME HOSE AROUND LOWER PART OF BOOM: CRACKED E/GのON/OFF関係なくバッテリーの周りからピッピッと音がする (センサーS/Wを押している間止まる) AROUND BATTERY: NOISES LIKE BEEP-BEEP EVEN ENGINE IS RUNNING OR NOT (ABLE TO STOP THE NOISE DURING PUSHING THE SENSOR SWITCH LEVER) 付属品: スケルトンバケット SKELETON BUCKET AS SPARE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。