## INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTIO	ON DATE	2025/8/22			M	MAKE K		KOMATSU		MODEL		CD20R-1		
SERIAL	1028							STAMP						
HR METER	3071 HR Odome				Odomet	neter			k	km ,	YEAR			YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP NON						NONE	SHOE		320F	₹	TIRE		
ENGINE: MODEL S/N								MAIN FRAME						
Oil leakage	FAIR · Attn							MAIN FLAME FAIR - Attn						
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE							VESSEL						
Sound	FAIR · Attn							VESSE	L	FAIR	<ul> <li>Attn</li> </ul>			
Oil	FAIR · Attn							REAR GATE	TYP€	N	ORMAL		GATE (FLAT)	
Exhaust Color	FAIR · Attn							REAR GA	ATE	FAIR	<ul> <li>Attn</li> </ul>			
US EPA	YES · NO							UNDERCARRIAGE: See Photos. 写真参照						
OPERATION PUMP							RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 5							
Sound	FAIR · Attn							TIRE WE	AR (	FA	JR •W	ORN · UI	NEVEN WEAR	
Oil leakage	FAIR · Attn							COMMENT	-					
Power	FAIR · Attn							リペイントま	あり R	EPA	INTED			
COOLING SYSTEM								CNP屋根欠 CNP TOP: MISSING						
Radiator	FAIR · Attn													
Oil Cooler	FAIR · Attn													
TRANSMIS	TRANSMISSION & TRAVEL													
T/M TYPE	PS) · DD				No. OF GEA	RS -	GEARS							
Transmission	FAIR · Attn					•								
Travel	FAIR · Attn													
Swing	FAIR · Attn													
Articulate	FAIR · Attn													
FOOT BRAKE	FAIR · Attn													
PARKING BRAKE	FAIR · Attn													
INTERIOR See Photos. 写真参照														
INTERIOR COND.	CLEAN	>	FAIR	•	DIRTY	,								
Operator's Seat	FAIR · Attn													
Glasses	FAIR · Attn													
AirCon	A/C ·	H/C	• H	only	• C on	ly •(I	None	RUST of BODY	(5: NONE	, 4: A L	ITTLE, 3: N	MIDDLE, 2: MU	CH, 1: CORRODED)	5

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。