

INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2025/8/25	CATEGORY	<u>ON-ROAD DUMP</u> • OFF-ROAD DUMP	
MAKE	KOMATSU		MODEL	HM300-2
SERIAL	2682		STAMP	KMTHM005E26002682
HR METER	6472	HR	ODOMETER	25880 km
TIRE SIZE	750/65R25		YEAR	2004 YR

ENGINE : MODEL 6D125E-5 S/N 566056			
Oil leakage	<u>FAIR</u> • Attn		
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	<u>FAIR</u> • Attn		
Oil	<u>FAIR</u> • Attn		
Exhaust Color	<u>FAIR</u> • Attn		
US EPA	<u>YES</u> • NO		
OPERATION PUMP			
Sound	<u>FAIR</u> • Attn		
Oil leakage	<u>FAIR</u> • Attn		
Power	<u>FAIR</u> • Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> • Attn		
Oil Cooler	<u>FAIR</u> • Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<u>AT</u> • MT	No. OF GEARS	5 GEARS
Transmission	<u>FAIR</u> • Attn		
4WD	4WD • <u>2WD</u>		
Travel	<u>FAIR</u> • Attn		
Articulate	<u>FAIR</u> • Attn		
FOOT BRAKE	<u>FAIR</u> • Attn		
PARKING BRAKE	<u>FAIR</u> • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY		
Operator's Seat	<u>FAIR</u> • Attn	破れあり MUCH WORN	
Glasses	<u>FAIR</u> • Attn		
AirCon	<u>A/C</u> • H/C • H only • C only • None		

MAIN FRAME	
MAIN FLAME	<u>FAIR</u> • Attn
VESSEL	
MAKE	
VESSEL	<u>FAIR</u> • Attn
REAR GATE TYPE	NORMAL • L-GATE (FLAT)
REAR GATE	<u>FAIR</u> • Attn
UNDERCARRIAGE: See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR • WORN • <u>UNEVEN WEAR</u>
COMMENT	
ROPS CAB	
アクセル踏み込むとE/G警告灯が点灯する (ほぼ100%出ているが消える時もある)	
ENGINE WARNING LAMP:	
ALMOST ALWAYS ON AFTER STEPPING ON THE ACCELERATOR PEDAL (SELDOM TURNING OFF)	
アクセルを踏み込んでいる間CABが小刻みに大きく揺れる	
CAB: SHAKING DURING STEPPING ON THE ACCELERATOR PEDAL	
右前方真上付近油漏れあり	
AROUND TOP FRONT RIGHT PART OF BODY: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。