INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/3/6	MAKE	HITACHI	MODEL	LX130-7
SERIAL	4G0P000216			STAMP	S32-00216
HR METER	4432 HR	Odometer	3438+27979 km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	黒煙小あり BLACK FUMES
US EPA	YES・NO	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	水漏れあり WATER LEAKING
Oil Cooler	FAIR・Attn	コア補修跡あり REPAIRED
TRANSMISSION & TRAVEL		
T/M TYPE	PS・DD	
Transmission	FAIR・Attn	
Travel	FAIR・Attn	
FOOT BRAKE	FAIR・Attn	
PARKING BRAKE	FAIR・Attn	
INTERIOR	See Photos. 写真参照	
INTERIOR COND.	CLEAN・FAIR・DIRTY	
Operator's Seat	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
FRONT & CYLINDERS		
Arm	FAIR・Attn	
Bell crank	FAIR・Attn	
Bucket	FAIR・Attn	
Articulate	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
TIRE WEAR	FAIR・WORN・UNEVEN WEAR	
COMMENT		
STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES・NO	
ATTACHMENTS		
STD BKT	YES・OTHER	マルチプラウ MULTI PLOW
BLADE	YES・NO	Piping for Tilt YES・NO
COMMENT		
CAB穴、雨漏り、左ドア閉まらない		
CAB: HOLES, LOOF LEAKING, LEFT DOOR: MALFUNCTION TO SHUT		
マルチプラウの右側シリンダー油漏れあり		
RIGHT CYLINDER OF MULTI PLOW: OIL LEAKING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。