

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/25	MAKE	KOMATSU	MODEL	PC300LC-11
SERIAL	91441			STAMP	KMTPC256LLC091441
HR METER	11519	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	800G

ENGINE : MODEL 6D114E-6 **S/N** 26910995

Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	

MAIN PUMP

Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	

COOLING SYSTEM

Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	

OPERATING SYSTEM

Swing	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	☒ CLEAN	FAIR · DIRTY
Operator's Seat	☒ FAIR	Attn
Glasses	☒ FAIR	Attn
AirCon	☒ A/C	H/C · H only · C only · None

BOOM / ARM / BKT

Boom	☒ FAIR	Attn	
Boom Cylinder	☒ FAIR	Attn	
Arm	☒ FAIR	Attn	
Arm Cylinder	☒ FAIR	Attn	
ATTACHMENT	☒ FAIR	Attn	
BKT Cylinder	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENT

.....

.....

.....

.....

BKT ☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER ()

Lever LONG · ☒ WRIST

Multi ☒ MULTI · 2 · NO

ARM-CRANE YES · ☒ NO

BLADE YES · ☒ NO

OFFSET YES · ☒ NO

OFFSET Cylinder FAIR · Attn

Piping YES · ☒ NO Breaker only · Multi

COMMENT

各種故障警告あり ※要写真参照

"L01" ERRORS DISPLAY FOR UREA SCR SYSTEM

.....

.....

.....

.....

.....

.....

.....

.....

.....

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。