

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/21	MAKE	KOMATSU	MODEL	WA100-5		
SERIAL	70334			STAMP	W108-70334		
HR METER	24092	HR	Odometer	167159	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			TIRE SIZE	15.5-25		

ENGINE : MODEL 4D102E-2 S/N 26334851					
Oil leakage	(FAIR)	Attn			
Blow-By	(FAIR)	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	(FAIR)	Attn			
Oil	(FAIR)	Attn			
Exhaust Color	(FAIR)	Attn			
US EPA	(YES)	NO			
OPERATION PUMP					
Sound	(FAIR)	Attn			
Oil leakage	(FAIR)	Attn			
Power	(FAIR)	Attn			
COOLING SYSTEM					
Radiator	(FAIR)	Attn			
Oil Cooler	(FAIR)	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	(PS)	DD			
Transmission	(FAIR)	Attn			
Travel	(FAIR)	Attn			
FOOT BRAKE	(FAIR)	Attn	*1		
PARKING BRAKE	FAIR	(Attn)	効かない	MALFUNCTION	
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN ·	(FAIR) ·	DIRTY		
Operator's Seat	(FAIR)	Attn			
Glasses	FAIR	Attn			
AirCon	A/C · H/C · H only · C only ·	(None)			
FRONT & CYLINDERS					
Arm	(FAIR)	Attn			
Bell crank	(FAIR)	Attn			
Bucket	(FAIR)	Attn			
Articulate	(FAIR)	Attn			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR					
COMMENT					
STEERING TYPE (WHEEL STEERING) / COMMAND STEERING / LEVER STEERING					
RIDE CONTROL YES · (NO)					
ATTACHMENTS					
STD BKT		YES · (OTHER)	フォーク FORK (LENGTH: 1630mm)		
BLADE		YES · (NO)	Piping for Tilt	YES ·	(NO)
COMMENT					
*1 ペダル破損あり(ブレーキは効く) PEDAL: BROKEN (BRAKE: OK)					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。