

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/9/3	MAKE	MITSUBISHI	MODEL	BD2G
SERIAL	2B103467			STAMP	2B103467
HR METER	4137	HR	SHOE	500LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR • Attn</td> </tr> <tr> <td>Blow-By</td> <td>FAIR • Attn A LITTLE • MIDDLE • SEVERE</td> </tr> <tr> <td>Sound</td> <td>FAIR • Attn</td> </tr> <tr> <td>Oil</td> <td>FAIR • Attn</td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR • Attn</td> </tr> <tr> <td>US EPA</td> <td>YES • NO</td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td>FAIR • Attn</td> </tr> <tr> <td>Oil leakage</td> <td>FAIR • Attn</td> </tr> <tr> <td>Power</td> <td>FAIR • Attn</td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td>FAIR • Attn</td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR • Attn</td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td>PS • DD DIFF. STEERING YES • NO</td> </tr> <tr> <td>Transmission</td> <td>FAIR • Attn</td> </tr> <tr> <td>Travel</td> <td>FAIR • Attn</td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND.</td> <td>CLEAN • FAIR • DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR • Attn 破れあり CUTS</td> </tr> <tr> <td>Glasses</td> <td>FAIR • Attn</td> </tr> <tr> <td>AirCon</td> <td>A/C • H/C • H only • C only • None</td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE</td> <td>FAIR • Attn</td> </tr> <tr> <td>CYLD.(R)</td> <td>FAIR • Attn</td> </tr> <tr> <td>CYLD.(L)</td> <td>FAIR • Attn</td> </tr> <tr> <td>TILT CYLD</td> <td>FAIR • Attn</td> </tr> <tr> <td>ANGLE CYLD</td> <td>FAIR • Attn 油にじみあり OIL OOZING</td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage	FAIR • Attn	Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE	Sound	FAIR • Attn	Oil	FAIR • Attn	Exhaust Color	FAIR • Attn	US EPA	YES • NO	OPERATION PUMP		Sound	FAIR • Attn	Oil leakage	FAIR • Attn	Power	FAIR • Attn	COOLING SYSTEM		Radiator	FAIR • Attn	Oil Cooler	FAIR • Attn	TRANSMISSION & TRAVEL		T/M TYPE	PS • DD DIFF. STEERING YES • NO	Transmission	FAIR • Attn	Travel	FAIR • Attn	INTERIOR See Photos. 写真参照		INTERIOR COND.	CLEAN • FAIR • DIRTY	Operator's Seat	FAIR • Attn 破れあり CUTS	Glasses	FAIR • Attn	AirCon	A/C • H/C • H only • C only • None	BLADE & CYLINDERS		BLADE	FAIR • Attn	CYLD.(R)	FAIR • Attn	CYLD.(L)	FAIR • Attn	TILT CYLD	FAIR • Attn	ANGLE CYLD	FAIR • Attn 油にじみあり OIL OOZING	<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>3</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td>Ripper</td> <td>MULTI • S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>FAIR • Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">プッシュアーム亀裂あり PUSH ARM: CRACKED</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">2</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	COMMENT												Ripper	MULTI • S/S Shanks PCS	Ripper CYLD.	FAIR • Attn	COMMENT		プッシュアーム亀裂あり PUSH ARM: CRACKED																				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2	
ENGINE : MODEL	S/N																																																																																																								
Oil leakage	FAIR • Attn																																																																																																								
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE																																																																																																								
Sound	FAIR • Attn																																																																																																								
Oil	FAIR • Attn																																																																																																								
Exhaust Color	FAIR • Attn																																																																																																								
US EPA	YES • NO																																																																																																								
OPERATION PUMP																																																																																																									
Sound	FAIR • Attn																																																																																																								
Oil leakage	FAIR • Attn																																																																																																								
Power	FAIR • Attn																																																																																																								
COOLING SYSTEM																																																																																																									
Radiator	FAIR • Attn																																																																																																								
Oil Cooler	FAIR • Attn																																																																																																								
TRANSMISSION & TRAVEL																																																																																																									
T/M TYPE	PS • DD DIFF. STEERING YES • NO																																																																																																								
Transmission	FAIR • Attn																																																																																																								
Travel	FAIR • Attn																																																																																																								
INTERIOR See Photos. 写真参照																																																																																																									
INTERIOR COND.	CLEAN • FAIR • DIRTY																																																																																																								
Operator's Seat	FAIR • Attn 破れあり CUTS																																																																																																								
Glasses	FAIR • Attn																																																																																																								
AirCon	A/C • H/C • H only • C only • None																																																																																																								
BLADE & CYLINDERS																																																																																																									
BLADE	FAIR • Attn																																																																																																								
CYLD.(R)	FAIR • Attn																																																																																																								
CYLD.(L)	FAIR • Attn																																																																																																								
TILT CYLD	FAIR • Attn																																																																																																								
ANGLE CYLD	FAIR • Attn 油にじみあり OIL OOZING																																																																																																								
UNDERCARRIAGE See Photos. 写真参照																																																																																																									
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																																								
COMMENT																																																																																																									
Ripper	MULTI • S/S Shanks PCS																																																																																																								
Ripper CYLD.	FAIR • Attn																																																																																																								
COMMENT																																																																																																									
プッシュアーム亀裂あり PUSH ARM: CRACKED																																																																																																									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																									
2																																																																																																									

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。