

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/8	MAKE	HITACHI	MODEL	ZX500LCK-6
SERIAL	HCMJAGA6L00060496			STAMP	HCMJAGA6L00060496
HR METER	6908	HR	YEAR	2018	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		6UZ1	S/N	529907
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only • None
BOOM / ARM / BKT				
Boom	FAIR	Attn	2ピースブーム 2-PIECE BOOM (LENGTH: 13.4m)	
Boom Cylinder	FAIR	Attn	右側にじみあり RIGHT CYLINDER: OIL OOZING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	溶接跡あり WELDED	
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi 7
COMMENT	
左サイドカバーヒンジ破損あり、ラッチかからない	
SOME LEFT SIDE COVER HINGE: BROKEN, LATCH: UNABLE TO CATCH	
一部カメラ映らない MONITOR CAMERA: PARTLY NOT DISPLAYING	
ワンタッチ付 W/ONE-TOUCH	
付属品: 台座 FIXING STAND AS SPARE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。