

INSPECTION SHEET 検品書
TRUCKトラック

INSPECTION DATE	2025/8/27	MAKE	HINO	MODEL	FS1ERB
SERIAL	10240			STAMP	FS1ERB-10240
HR METER	HR			Odometer	371833 km
TIRE	11R22.5			YEAR	YR

ENGINE : MODEL		S/N	
Oil leakage	☒ FAIR · Attn		
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR · Attn		
Oil	☒ FAIR · Attn		
Exhaust Color	☒ FAIR · Attn		
US EPA	YES · ☒ NO		
OPERATION PUMP			
Sound	☒ FAIR · Attn		
Oil leakage	☒ FAIR · Attn		
Power	☒ FAIR · Attn		
COOLING SYSTEM			
Radiator	☒ FAIR · Attn		
Oil Cooler	☒ FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	AT · ☒ MT	No. OF GEARS	7 GEARS
Transmission	☒ FAIR · Attn		
4WD	4WD · ☒ 2WD		
Travel	☒ FAIR · Attn		
FOOT BRAKE	☒ FAIR · Attn		
PARKING BRAKE	☒ FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY		
Operator's Seat	☒ FAIR · Attn		
Glasses	☒ FAIR · Attn		
AirCon	☒ A/C · H/C · H only · C only · NONE		
OUTRIGGERS / JACK			
OUTRIGGERS	X · H		
CONDITION	☒ FAIR · Attn		
JACK	☒ FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR			
COMMENT			
BODY			
CATEGORY		ARM-ROLL	
MAKE		KYOKUTO	
MODEL	JM10-53X	SERIAL	12H050020M
CONDITION	☒ FAIR · Attn		
MAIN FRAME	☒ FAIR · ☒ Attn	錆びあり RUSTY	
CRANE			
MAKE			
MODEL		SERIAL	
No. of Section	SECTIONS		
HOOK			
RADIO CONTROL	YES · ☒ NO		
COMMENT			
箱なし WITHOUT CONTAINER			
リモートコントロールあり W/REMOTE CONTROL			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。