

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/8	MAKE	KUBOTA	MODEL	U40-6
SERIAL	11736		STAMP	11736	
HR METER	2215	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	400G PADS	

ENGINE : MODEL		V2607	S/N	8CW3865
Oil leakage	<u>FAIR</u> · Attn			
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	<u>FAIR</u> · Attn			
Oil	<u>FAIR</u> · Attn			
Exhaust Color	<u>FAIR</u> · Attn			
US EPA	<u>YES</u> · NO			
MAIN PUMP				
Sound	<u>FAIR</u> · Attn			
Oil leakage	<u>FAIR</u> · Attn			
Power	<u>FAIR</u> · Attn			
COOLING SYSTEM				
Radiator	<u>FAIR</u> · Attn			
Oil Cooler	<u>FAIR</u> · Attn			
OPERATING SYSTEM				
Swing	<u>FAIR</u> · Attn			
Travel	<u>FAIR</u> · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY			
Operator's Seat	<u>FAIR</u> · Attn			
Glasses	<u>FAIR</u> · Attn			
AirCon	A/C · H/C · <u>H only</u> · C only · None			
BOOM / ARM / BKT				
Boom	<u>FAIR</u> · Attn			
Boom Cylinder	<u>FAIR</u> · Attn			
Arm	<u>FAIR</u> · Attn			
Arm Cylinder	<u>FAIR</u> · Attn			
BKT	<u>FAIR</u> · Attn			
BKT Cylinder	<u>FAIR</u> · Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。