

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/8	MAKE	KOMATSU	MODEL	PC130-6E
SERIAL	52213		STAMP	PC130-052213	
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL 4D102E-1 **S/N** 26264639

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 切れあり HUGE CUTS
Glasses	FAIR · Attn ドアガラスなし DOOR GLASS: MISSING
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

COMMENT

左右シュールリンク固着あり TRACK LINKS: STUCK
左右シュールリンク伸びあり TRACK LINKS: WORN

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
-----	---

Lever	LONG · WRIST
-------	--------------

Multi	MULTI · 2 · NO
-------	----------------

ARM-CRANE	YES · NO
-----------	----------

BLADE	YES · NO
-------	----------

OFFSET	YES · NO
--------	----------

OFFSET Cylinder	FAIR · Attn
-----------------	-------------

Piping	YES · NO Breaker only · Multi
--------	-------------------------------

COMMENT

モニター写らない MONITOR: MALFUNCTION

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。