## INSPECTION SHEET 検品書 ROLLER ローラー

INSPECTION	ON DATE	2025/9/2	MAKE	DYNAPAC			MODEL	CC222	
SERIAL	61710566			STAMP			NOT FOUND		
HR METER	1718 HR Odometer						km YEAR		YR
CAB/CNP	ROPS CA	AB / CAB / ROPS	CNP / CNP	NONE	TIRE SIZ	ZE	<b>!</b>		
ENGINE :	l	UNDERCARRIAGE: See Photos. 写真参照							
Oil leakage	FAIR · Attn				RUST (5: NON	IE, 4: A	LITTLE, 3: MID	DLE, 2: MUCH, 1: CORRODED)	3
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE				TIRE WEAR FAIR · WORN · UNEVEN WEAR				
Sound	FAIR · Attn				COMMENT				
Oil	FAIR · Attn				不動機 IMMOVABLE MACHINE				
Exhaust Color	FAIR · Attn	電気系統不良のためセルモーターが回りっぱなしになる							
US EPA	YES · (NO				そのためエ	ンジン	ノをすぐに」	上めなければならない	
OPERATION PUMP					ENGINE: UNABLE TO KEEP RUNNING, NEED TO STOP				
Sound	FAIR · Attn				(ELECTRIC	SYS	TEM: MAL	FUNCTION,	
Oil leakage	FAIR · Attn				STARTER	МОТ	OR: KEEPI	ng running)	
Power	FAIR · Attn								
COOLING	SYSTEM								
Radiator	FAIR · Attn								
Oil Cooler	FAIR · Attn								
TRANSMIS									
T/M TYPE	PS · DD								
Transmission	FAIR · Attn								
Travel	FAIR · Attn								
FOOT BRAKE	FAIR · Attn								
PARKING BRAKE	FAIR · Attn								
INTERIOR See Photos. 写真参照									
INTERIOR COND.	CLEAN	· FAIR ·	DIRTY						
Operator's Seat	FAIR · Attn	切れあり HUGE C	UTS						
Glasses	FAIR · Attn								
AirCon	A/C ·	H/C • H only	· C only ·(	None					
OTHERS									
Vibratory	FAIR · Attn								
Watering	FAIR · Attn								

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)

Articulate FAIR · Attn