

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/16	MAKE	HKN	MODEL	HK130S
SERIAL	HK130S-50242			STAMP	HK130S-50242
HR METER	2534	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE		8.25R16 14PR (SPIKE, SNOW)	

ENGINE : MODEL S6F S/N 002186	
Oil leakage	FAIR · <u>Attn</u> 周りにじみあり AROUND ENGINE: OIL OOZING
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · <u>NO</u>
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<u>PS</u> · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	<u>A/C</u> · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · Attn
Bell crank	FAIR · Attn
Bucket	FAIR · Attn
Articulate	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR <u>FAIR</u> · WORN · UNEVEN WEAR	
COMMENT	
下周りホースにじみあり SOME HOSE OF BOTTOM: OIL OOZING	
タコメーター TACHOMETER: 65464km	
STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · <u>NO</u>
ATTACHMENTS	
STD BKT	YES · <u>OTHER</u> ロータリー ROTARY SNOW PLOW
BLADE	YES · <u>NO</u> Piping for Tilt YES · <u>NO</u>
COMMENT	
A/C故障あり A/C: MALFUNCTION	
除雪巾 PLOWING WIDTH : 1,500mm	
草刈装置取付可	
ABLE TO ATTACH THE GRASS CUTTER ON THIS AUCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。