

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/8	MAKE	KATO	MODEL	HD823MRLC-6
SERIAL	KWJ25EL1PF0005117		STAMP	5117	
HR METER	12359	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		4M50	S/N
Oil leakage	(FAIR) · Attn		
Blow-By	FAIR (Attr)	(A LITTLE) MIDDLE · SEVERE	
Sound	FAIR (Attr)	タペット音あり NOISES FROM TAPPET	
Oil	(FAIR) · Attn		
Exhaust Color	(FAIR) · Attn		
US EPA	YES (NO)		
MAIN PUMP			
Sound	(FAIR) · Attn		
Oil leakage	(FAIR) · Attn		
Power	(FAIR) · Attn		
COOLING SYSTEM			
Radiator	(FAIR) · Attn		
Oil Cooler	(FAIR) · Attn		
OPERATING SYSTEM			
Swing	(FAIR) · Attn		
Travel	(FAIR) · Attn		
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY		
Operator's Seat	(FAIR) · Attn		
Glasses	FAIR (Attr)	ドアガラス破損あり DOOR GLASS: BROKEN	
AirCon	(A/C) · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	(FAIR) · Attn		
Boom Cylinder	(FAIR) · Attn		
Arm	(FAIR) · Attn		
Arm Cylinder	(FAIR) · Attn		
BKT	(FAIR) · Attn		
BKT Cylinder	(FAIR) · Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · (WRIST)		
Multi	MULTI · 2 · (NO)		
ARM-CRANE	(YES) · NO		
BLADE	YES · (NO)		
OFFSET	YES · (NO)		
OFFSET Cylinder	FAIR · Attn		
Piping	YES · (NO)	Breaker only · Multi	
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。