

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/22	MAKE	KOMATSU	MODEL	PC228US-3N0
SERIAL	30037			STAMP	PC228-030037
HR METER	UNKNOWN		HR	YEAR	YR
CAB/CNP	ROPS CAB	☒ CAB	ROPS CNP	CNP	NONE
			SHOE	800G	

ENGINE : MODEL 6D102E-2 S/N 26310668	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	☒ YES · NO
MAIN PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn 油漏れあり OIL LEAKING
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
OPERATING SYSTEM	
Swing	☒ FAIR · Attn
Travel	☒ FAIR · Attn 増速不良 HIGH SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn 破れあり TORN
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	☒ FAIR · Attn
Boom Cylinder	☒ FAIR · Attn
Arm	☒ FAIR · Attn
Arm Cylinder	☒ FAIR · Attn
BKT	☒ FAIR · Attn 穴、ガタあり CRACKED, LOOSE
BKT Cylinder	☒ FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · ☒ WRIST
Multi	MULTI · 2 · ☒ NO
ARM-CRANE	☒ YES · NO *1
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · ☒ NO Breaker only · Multi
COMMENT	
A/Cコンデンサーフィン破損あり A/C CAPACITOR FINS: PARTLY BROKEN	
A/C冷えない A/C: MALFUNCTION	
エアクリーナーボックス穴、脱落あり	
AIR CLEANER BOX: A LITTLE BROKEN, COME OFF	
ブーム背面ホースヒビあり	
SOME HOSES AROUND LOWER PART OF BOOM: CRACKED	
アクセルダイヤルを高回転にするとE/Gアイドルリングが安定しない (上がったたり下がったりする)	
ENGINE IDLE: UNSTABLE DURING REVING UP (FLUCTUATING)	
*1 ディスプレイ点かないためクレーンモード入らない	
*1 CRANE MODE: UNABLE TO TURN ON (MONITOR: NOT DISPLAYING)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。