

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/21	MAKE	HITACHI	MODEL	LX120-5
SERIAL	42GP003114 / DWL12HD569267			STAMP	L120H-569267
HR METER	36408	HR	Odometer	50117	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25 12PR (SNOW, SPIKE)

ENGINE : MODEL 6068HDW70 **S/N** T06068H781697

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS	DD	
Transmission	FAIR	Attn	
Travel	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	穴あり HOLE
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

FRONT & CYLINDERS

Arm	FAIR	Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	
Articulate	FAIR	Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

TIRE WEAR	FAIR · WORN · UNEVEN WEAR
-----------	---------------------------

COMMENT

タコメーター TACHOMETER: 10691km

STEERING TYPE	WHEEL STEERING / COMMAND STEERING / LEVER STEERING
---------------	--

RIDE CONTROL	YES · NO
--------------	----------

ATTACHMENTS

STD BKT	YES	OTHER	マルチプラウ MULTI PLOW
BLADE	YES	NO	Piping for Tilt YES · NO

COMMENT

ワンタッチ付 W/ONE-TOUCH

マルチプラウ溶接あり、左側底面ソリ欠

MULTI PLOW: WELDED, LEFT SLED: MISSING

付属品: スタンダードバケット STANDARD BUCKET AS SPARE

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。