

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/27	MAKE	KOBELCO	MODEL	SK45SR-6E
SERIAL	PH09021918			STAMP	PH09021918
HR METER	1230	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	400G

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> • Attn	
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE
Sound	<u>FAIR</u> • Attn	
Oil	<u>FAIR</u> • Attn	
Exhaust Color	<u>FAIR</u> • Attn	
US EPA	<u>YES</u> • NO	
MAIN PUMP		
Sound	<u>FAIR</u> • Attn	
Oil leakage	<u>FAIR</u> • Attn	
Power	<u>FAIR</u> • Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> • Attn	
Oil Cooler	<u>FAIR</u> • Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> • Attn	
Travel	<u>FAIR</u> • Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY	
Operator's Seat	<u>FAIR</u> • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • <u>None</u>	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> • Attn	
Boom Cylinder	<u>FAIR</u> • Attn	
Arm	<u>FAIR</u> • Attn	
Arm Cylinder	<u>FAIR</u> • Attn	
ATTACHMENT	<u>FAIR</u> • Attn	
BKT Cylinder	<u>FAIR</u> • Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	<u>MULTI</u> • 2 • NO
ARM-CRANE	YES • <u>NO</u>
BLADE	<u>YES</u> • NO
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	YES • <u>NO</u> Breaker only • Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。