

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/12	MAKE	HITACHI	MODEL	ZX120
SERIAL	HCM1S100A00070192			STAMP	HCM1S100A00070192
HR METER	3918	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G PADS

ENGINE : MODEL		4BG1	S/N	917871
Oil leakage	FAIR · <u>Attn</u>	周りにじみあり AROUND ENGINE: OIL OOZING		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	<u>FAIR</u> · Attn			
Oil	<u>FAIR</u> · Attn			
Exhaust Color	<u>FAIR</u> · Attn			
US EPA	<u>YES</u> · NO			
MAIN PUMP				
Sound	<u>FAIR</u> · Attn			
Oil leakage	FAIR · <u>Attn</u>	ホースにじみあり SOME HOSES: OIL OOZING		
Power	<u>FAIR</u> · Attn			
COOLING SYSTEM				
Radiator	<u>FAIR</u> · Attn			
Oil Cooler	<u>FAIR</u> · Attn			
OPERATING SYSTEM				
Swing	<u>FAIR</u> · Attn			
Travel	<u>FAIR</u> · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · <u>DIRTY</u>			
Operator's Seat	FAIR · <u>Attn</u>	破れあり CUTS		
Glasses	<u>FAIR</u> · Attn			
AirCon	<u>A/C</u> · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	<u>FAIR</u> · Attn			
Boom Cylinder	<u>FAIR</u> · Attn			
Arm	<u>FAIR</u> · Attn			
Arm Cylinder	<u>FAIR</u> · Attn			
ATTACHMENT	<u>FAIR</u> · Attn	ガタあり LOOSE		
BKT Cylinder	FAIR · <u>Attn</u>	にじみあり OIL OOZING		

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。