

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/12	MAKE	CAT	MODEL	938F
SERIAL	8SM00509			STAMP	8SM00509
HR METER	14827 + 1759	HR	Odometer	—	km
				YEAR	1996 YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25 12PR (SNOW, SPIKE)

ENGINE : MODEL 3116 S/N 7TM06986	
Oil leakage	FAIR · ☒ Attn ヘッドカバーにじみあり HEAD COVER: OIL OOZING
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ Attn
Oil	☒ Attn
Exhaust Color	☒ Attn
US EPA	☒ YES · NO
OPERATION PUMP	
Sound	☒ Attn
Oil leakage	☒ Attn
Power	☒ Attn
COOLING SYSTEM	
Radiator	☒ Attn
Oil Cooler	☒ Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS · DD
Transmission	☒ Attn
Travel	☒ Attn
FOOT BRAKE	☒ Attn
PARKING BRAKE	☒ Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	FAIR · ☒ Attn 破れ大 TORN
Glasses	FAIR · ☒ Attn *1
AirCon	☒ A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	☒ Attn
Bell crank	☒ Attn
Bucket	☒ Attn
Articulate	☒ Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR	
COMMENT	
下周りにじみあり BOTTOM: OIL OOZING	
タコメーター TACHOMETER: 38488km	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES · NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	☒ YES · NO Piping for Tilt ☒ YES · NO
COMMENT	
ワンタッチ付 W/ONE-TOUCH	
アイスパーンカッター ICY ROAD CUTTER	
付属品: マルチプラウ MULTI PLOW AS SPARE	
*1 F窓クラック、補修テープあり	
*1 WINDSHIELD: CRACKED, COVERED WITH ADHESIVE TAPES	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。