

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2025/9/30	MAKE	KOMATSU	MODEL	JV100A-1		
SERIAL	10363		STAMP	J10A-10363			
HR METER	3297	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.1-26		

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	*1
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	効かない MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
OTHERS		
Vibratory	FAIR · Attn	*2
Watering	FAIR · Attn	
Articulate	FAIR · Attn	*3

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT		
全体的にホースひび割れあり MANY HYDRAULIC HOSES: CRACKED エンジンONのままイグニッションキーをOFFにすると振動する、ONにすると止まる VIBRATION: WORKING WHEN TURNING OFF THE ENGINE BY THE IGNITION KEY, ABLE TO STOP TO WORK WHEN TURNING ON THE ENGINE BY THE KEY *1 1速から変えられない *1 UNABLE TO CHANGE ANY GEARS, LOCKED AT THE 1st GEAR *2 レバーLに入った状態で固定、Hに入らない *2 LEVER: LOCKED AT THE LOW SIDE (UNABLE TO TURN TO HIGH) *3 左右シリンダーメッキ剥がれあり、右側油漏れ小 *3 CYLINDERS: COATING PEELED, RIGHT CYLINDER: OIL LEAKING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。