

DUMP TRUCK ダンプ

INSPECTION DATE		2025/9/11	CATEGORY	ON-ROAD DUMP • OFF-ROAD DUMP	
MAKE	MITSUBISHI			MODEL	KC-FV509JXD
SERIAL	510573			STAMP	FV509JX-510573
HR METER	UNKNOWN		HR	ODOMETER	876160 km
TIRE SIZE	11R22.5 14PR			YEAR	YR

ENGINE : MODEL		8DC11	S/N	Z5521
Oil leakage	FAIR · <u>Attn</u>	ヘッドカバーにじみあり HEAD COVER: OIL OOZING		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	<u>FAIR</u> · Attn			
Oil	<u>FAIR</u> · Attn			
Exhaust Color	<u>FAIR</u> · Attn			
US EPA	YES · <u>NO</u>			
OPERATION PUMP				
Sound	<u>FAIR</u> · Attn			
Oil leakage	FAIR · <u>Attn</u>	上部にじみあり UPPER PART: OIL OOZING		
Power	<u>FAIR</u> · Attn			
COOLING SYSTEM				
Radiator	<u>FAIR</u> · Attn			
Oil Cooler	<u>FAIR</u> · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	AT · <u>MT</u>		No. OF GEARS	7 GEARS
Transmission	<u>FAIR</u> · Attn			
4WD	4WD · <u>2WD</u>			
Travel	<u>FAIR</u> · Attn	6・7速未確認 6th & 7th GEARS: NOT CHECKED		
Articulate	FAIR · Attn			
FOOT BRAKE	<u>FAIR</u> · Attn			
PARKING BRAKE	<u>FAIR</u> · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY			
Operator's Seat	FAIR · <u>Attn</u>	破れ、穴あり CUT, HOLES		
Glasses	<u>FAIR</u> · Attn			
AirCon	<u>A/C</u> · H/C · H only · C only · None			

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。