

INSPECTION SHEET 検品書

OTHER その他

INSPECTION DATE	2025/10/28	CATEGORY	パイルドライバー PILE DRIVER			
MAKE	NIPPON SHARYO			MODEL	DHP-80	
SERIAL	C80089			STAMP	C80089	
HR METER	5693	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB	CAB	ROPS CNP / CNP / NONE	SHOE	760FLAT	TIRE

ENGINE	MODEL			S/N		
Oil leakage	FAIR	Attn		Oil	FAIR	Attn
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	FAIR	Attn
Sound	FAIR	Attn		EPA	YES	NO

CONDITION	FAIR	Attn	
未確認 OPERATION: NOT CHECKED			
左フアウトリガーにじみあり FRONT LEFT OUTRIGGER: OIL OOZING			

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT			
ヒーター HEATER			
@SAKURA YARD			
LEADER TOP: 1.3m + 3m + 3m + 3m, INSERT: 1.5m + 3.7m + 1.3m, BOTTOM: 0.9m + 5.5m + 1.5m			
LEADER END, BACK STAY: (3.2m + 2.6m + 2.1m + 2.1m) × 2, LEADER JACK STAND × 2, WEIGHT × 2, LEADER FRAME × 1			
STEP × 1, BRACKET × 1, TOOL BOX × 1, AUGER (1 AXIS, MAKE: SANWA D50H), SWITCHBOARD			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。