

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/17	MAKE	KOBELCO	MODEL	SK200-8
SERIAL	YN12-64260		STAMP	YN12-64260	
HR METER	13457	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	左右油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :						See Photos. 写真参照						
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								2				
COMMENT												
BKT	(STD)	/ SLOPE / NARROW / SKELETON / OTHER()										
Lever	LONG ▪	(WRIST)										
Multi	(MULTI) ▪	2 ▪ NO										
ARM-CRANE	YES ▪	(NO)										
BLADE	YES ▪	(NO)										
OFFSET	YES ▪	(NO)										
OFFSET Cylinder	FAIR ▪	Attn										
Piping	YES ▪	(NO)	Breaker only ▪ Multi									
COMMENT												
ブーム下ホース破れあり SOME HOSES AROUND LOWER PART OF BOOM: MUCH CRACKED C013表示あり “C013” ERROR DISPLAY ローアイドル時リリース掛けるとエンストする ENGINE STALLING WITH ENGINE LOAD INCREASING WHEN LOW IDLING A/C風出ない A/C: NOT BLOWING AIR												
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)									2			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。