INSPECTION SHEET 検品書 LIFTING PLATFORM 高所作業車

INSPECTIO	N DATE	2025/9/2	1 MAKI	≣	AICHI		MODEL	SR21A		
SERIAL No.	PLATE :	700224			STAMP:	STAMP: NOT FOUND				
HR METER	541	1 HR	Odometer		_	ļ	km YEAR		YR	
CHASSIS	MODEL –			No. –						
SHOE	500G PADS			TIRE SIZ	E					
MAX HIGHT	21.0 m			MAX WEIG	НТ		200	kg		
ENGINE :	NGINE: MODEL 4JG1 S/N 315423					INTERIOR See Photos. 写真参照				
Oil leakage	FAIR · Attn				INTERIOR COND. CLEAN - FAIR - DIRTY					
Blow-By	FAIR) · Attn A LITTLE • MIDDLE • SEVERE				Operator's Seat FAIR · Attn					
Sound	FAIR · Attn				Glasses	FAIR •	Attn			
Oil	FAIR · Attn				AirCon A/C · H/C · H only · C only · None					
Exhaust Color	FAIR · Attn	• Attn				UNDERCARRIAGE: See Photos. 写真参照				
US EPA	YES)· NO				RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3					
OPERATION PUMP					TIRE WEAR FAIR · WORN · UNEVEN WEAR					
Sound	FAIR · Attn				COMMENT					
Oil leakage	FAIR · Attn									
Power	FAIR) · Attn									
COOLING SYSTEM					OUTRIGGERS X · H					
Radiator	FAIR · Attn				OUTRIGGERS (COND.	FAIR • Attn			
Oil Cooler	FAIR) · Attn				COMMENT					
TRANSMISSION & TRAVEL					機体外装リペイントあり REPAINTED					
T/M TYPE	АТ · мт		No. OF GEARS	GEARS						
Transmission	FAIR • Attn									
4WD	4WD • 2WD									
Travel	FAIR · Attn									
Swing	FAIR · Attn									
FOOT BRAKE	FAIR · Attn									
PARKING BRAKE FAIR • Attn										
воом										
No. of Section 3 SECTIONS										
DERRICKING CYL. FAIR · Attn										
EXTENSION CYL. FAIR · Attn					RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。