

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/23	MAKE	TADANO	MODEL	TR-100M-1
SERIAL No.	PLATE : FC0182		STAMP : TR100-0182		
HR METER	11538	HR	Odometer	100822	km
TIRE SIZE	11R22.5		YEAR	1995	YR

[illegible]

BOOM					
No. of Section	6 SECTIONS				
CRACK/ENFORCEMENT	(FAIR) ▪ Attn				
DERRICKING CYL.	(FAIR) ▪ Attn				
EXTENSION CYL.	(FAIR) ▪ Attn				
JIB	YES ▪ (NO)				
JIB TYPE	STD ▪ PWR				
MAIN & SUB WIRE	(YES) ▪ NO				
FREE FALL	(YES) ▪ NO				
HOOK	10t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					3
TIRE WEAR	(FAIR) ▪ WORN ▪ UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	(X) ▪ H				
OUTRIGGERS COND.	(FAIR) ▪ Attn				
Oil leakage (JACK CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
Oil leakage (SLIDE CYL.)	FRONT	L ▪ R	REAR	L ▪ R	
COMMENT					
*1 E/Gヘッド油漏れあり CYLINDER HEAD: OIL LEAKING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。