

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2025/9/5	CATEGORY	A SET OF SHOE LINK ASSYS for 0.45m3				
MAKE	HITACHI		MODEL	-			
SERIAL	-		STAMP	-			
HR METER	-	HR	Odometer	km		YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G		TIRE	

ENGINE	MODEL	S/N			
Oil leakage	FAIR ・ Attn		Oil	FAIR ・ Attn	
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	FAIR ・ Attn	
Sound	FAIR ・ Attn		EPA	YES ・ NO	

CONDITION	FAIR	Attn			
未確認 OPERATION: NOT CHECKED					

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	-	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4		

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。