## INSPECTION SHEET 検品書 OTHER その他

INSPECTIO	N DATE	2025/9/5	ピラニアバケット PIRANHA BUCKET					
MAKE	ONODERA			MODEL	UNKNOWN			
SERIAL	NO PLATE			STAMP	NOT FOUND			
HR METER	- HR Odometer				km YEAR YR			
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE SHOE					TIRE		
ENGINE	MOD	EL	S/N					
Oil leakage	FAIR · Attn			Oil	FAIR • Attn			
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE			Exhaust Color	FAIR • Attn	AIR • Attn		
Sound	FAIR · Attn			EPA	YES • NO			
CONDITION FAIR - Attn								
未確認 OPERATION: NOT CHECKED								
UNDERCARRIAGE: See Photos. 写真参照								
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				TIRE WEA	AR FAIR • WORN • UNEVEN WEAR			
COMMENT								
$65\phi imes255$ mm								
取付ピン欠 NO PINS								
取付ホース2本あり W/2 HOSES								

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)