

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/6	MAKE	YANMAR	MODEL	V3-3			
SERIAL	31095			STAMP	L3B-31095			
HR METER	E3668	HR	Odometer	—	km	YEAR	1998	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	12.5/70-16			

ENGINE : MODEL		S/N	13724
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ▪ FAIR ▪ DIRTY				
Operator's Seat	FAIR	▪ Attn			
Glasses	FAIR	▪ Attn			
AirCon	A/C	▪ H/C	▪ H only	▪ C only	▪ None

FRONT & CYLINDERS

Arm	FAIR	Attn	
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	
Articulate	FAIR	Attn	シリンダー油漏れ小 CYLINDER: OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR (FAIR • WORN • UNEVEN WEAR)	

COMMENT

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	YES	☒	NO
--------------	-----	----------------------------------	----

ATTACHMENTS

STD BKT	YES • OTHER		
BLADE	YES • NO	Piping for Tilt	YES • NO

COMMENT

CAB右ドア室内レバー欠 INSIDE RIGHT DOOR KNOB: MISSING
HRメーターストップ HR METER: STOPPED

This image shows a blank sheet of white paper with horizontal ruling lines. A solid black vertical line runs down the left side, creating a margin. The rest of the page is filled with evenly spaced horizontal black lines. There are no markings or text on the page.

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。