INSPECTION SHEET 検品書 CRAWLER CRANE クローラクレーン

INSPECTION	DATE	2025/10/6	MAKE	.	SUMITOMO	MODEL	SCX700-2C3	
SERIAL No. PLATE: SC070-7149				STAMP	STAMP SC070-7149			
HR METER	261	60 HR	SHOE		760FLAT	YEAR		YR
ENGINE: MODEL S/N					INTERIOR See Photos. 写真参照			
Oil leakage FAIR) · Attn					INTERIOR COND. CLEAN - FAIR - DIRTY			
Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE					Operator's Seat FAIR Attn			
Sound FAIR · Attn					Glasses FAIR Attn			
Oil FAI	IR) · Attn				AirCon A/C)∙ н/с	· H only · C only ·	None
Exhaust Color FAIR · Attn				UNDERCARRIAGE: See Photos. 写真参照				
OPERATION PUMP					RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			
Sound FAIR · Attn				COMMENT				
Oil leakage FAI	IR) · Attn							
Power FAI	IR) · Attn							
COOLING SYSTEM				WEIGHT	3			
Radiator FAIR) · Attn				ноок	70t, 40t, 20t, BALL			
Oil Cooler FAI	IR) · Attn				FREE FALL	YE9 · NO		
OPERATING SYSTEM					LIFTER	YES · NO		
Computer OK · NG					COMMENT			
Swing FAI	IR) · Attn				@NARITA YARD			
Travel FAIR) · Attn				BOOM: TOP, BOTTOM, 6m×1, 3m×1				
ВООМ				70t HOOK				
MAIN BOO	ОМ	ТОР, ВОТТОМ,	9m×1, 6m×	3, 3m×3				
BOOM TOTAL		45m			@SAKURA YARD			
	·				BOOM: 9m × 1, 6	m × 2, 3m ×	2	
TOP SHEAVE YES . NO			HOOK: 40t, 20t, BALL					
JIB					TOWER: TOP, BOTTOM, 6m × 3, 3m × 1, CAP, SWING,			
					GUIDE	ROLLER,	A SET OF BRIDLE, CATO	CHER,
TOWER 42m + 31m		A SET OF PENDANTS, AUXILIARY HOISTING WIRE						
TOP, BC		BOTTOM, 6m×	OTTOM, 6m × 3, 3m × 1 RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODE					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。