

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/29	MAKE	KOMATSU	MODEL	WA100-1		
SERIAL	33318			STAMP	W005-33318		
HR METER	5055	HR	Odometer	23899	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24 10PR (SNOW)		

ENGINE : MODEL		6D95L-1	S/N	90101
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
OPERATION PUMP				
Sound	FAIR · Attn			
Oil leakage	FAIR · Attn			
Power	FAIR · Attn			
COOLING SYSTEM				
Radiator	FAIR · Attn			
Oil Cooler	FAIR · Attn			
TRANSMISSION & TRAVEL				
T/M TYPE	PS · DD			
Transmission	FAIR · Attn			
Travel	FAIR · Attn			
FOOT BRAKE	FAIR · Attn			
PARKING BRAKE	FAIR · Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN · FAIR · DIRTY			
Operator's Seat	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
FRONT & CYLINDERS				
Arm	FAIR · Attn	*1		
Bell crank	FAIR · Attn			
Bucket	FAIR · Attn			
Articulate	FAIR · Attn			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3
TIRE WEAR FAIR · WORN · UNEVEN WEAR				
COMMENT				
下周りにじみあり BOTTOM: OIL OOZING				
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING				
RIDE CONTROL YES · NO				
ATTACHMENTS				
STD BKT	YES · OTHER	フォーク+バケット FORK W/BUCKET		
BLADE	YES · NO	Piping for Tilt	YES · NO	
COMMENT				
ラジオ故障あり RADIO: MALFUNCTION				
*1 左シリンダーにじみ、右シリンダー油漏れあり				
*1 LEFT CYLINDER: OIL OOZING, RIGHT CYLINDER: OIL LEAKING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				
3				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。